

ARGYLE CREEK WATER COMMISSIONER'S REPORT

John Bene - Court Appointed Water Commissioner

August 12, 1963

Henry Mills: No water being diverted on either side of Argyle Creek. Diversion dams washed out by recent floods.

Umbert Pressett: 0.70 cfs. diverted. No control gate on diversion.


Neve Wimmer: 2.85 cfs. diverted.

Hayes Place (Brook operator) No water being diverted. Diversion dam washed out by recent floods.

Preston Nutter Corp.: No water being diverted on the south side; filled in by flood. North side diversion: 1.82 cfs. Commissioner estimates that in excess of 2½ ft. going over diversion dam.

The area in the past week has received heavy rains in the mountains and light showers in the valley. It is reported that three different floods went down Nine Mile Creek.

Crops all look good.



cc: Judge Joseph Nelson - Provo  
State Engineer - State Capitol - SLC  
Edward Clyde - 351 South State - SLC  
E. J. Skeen - 522 Newhouse Bldg. - SLC  
N. L. Wimmer - Nine Mile  
Preston Nutter Corp. - Nine Mile  
Clive Sprouse - Roosevelt  
Henry Mills - Price  
Umbert Pressett - Nine Mile

